


# Presumpscot River Landslide

## Prepared for Office of Governor Mills


October 2, 2020

by  
Portland Water District


# Area of Landslide




# Area of Landslide



# District Infrastructure







River edge  
looking back  
at slide

9/17



Warren Ave.  
side looking  
upstream

9/17



Mats in  
PWD ROW  
to access  
site


9/27



Debris atop  
water main  
and  
wastewater  
outfall


# Removing rootballs and trees





Tree “island”  
moved by  
slide,  
upstream of  
water mains

9/28



Clay in  
Riverbed

9/29

# Looking Downstream 9/29



# Looking Upstream 9/29



# Mulched Slope 9/29



# Upstream and Material atop Water Main 9/30



# Downstream 9/30



# Downstream 9/30



# Material atop Water Main across the River 9/30



# Upstream 9/30

